Section 1	MANAGEMEN	T OF	CHANGE	(MOC	;)			ABU:		Plant:	Year:
MOC	No: Originate	or:	Date Issued:	Passpoi	rt No:	EWO	No:	D&R		4 Crude	2012
257	789 Palumbo, Te	erry A.	11/17/2012	·							
Section 2 Reviewer: MOC Category:		PSM:			MOC Type:		Expiration Date:	Other 1	Temporary Reason		
Preciad	lo, Silvano E. S/[)				Permanent					
Project/Eq	uipment Title: 4 Crude Reco	very - Pro	cess Piping Syst	ems Materi	al Char	ges					
Description	of Change:										
	process piping damaged by	the 4 Crud	de Unit fire in 201	2. Includes	s the TA	W's that app	oly to th	e various process	piping	systems which had r	material
	g., 5CR to 9CR.										
	covers the upgrade of piping ms piping, and C 1100 inlet t			to 9 Chrom	ne. Ine	se piping sys	items in	clude 3 side cut, 4	4 side c	ut, repoller bypass p	iping, C-
TAW# - 17	271, 17311, 17312, 17531, 1			3, 17599, 1	7600, 1	7604, 17621	, 17622	, 17623, 17812, 1	7826, 1	7832, 17844, 17848,	, 17849,
18237, 183	319, and 18405.										
MOC will b	e required if the change will:										
Caus	se the use of different feed, c	nemicals	or catalysts?								
Caus	se the use of different proces	s conditio	ns, process contro	ol, instrume	ntation,	and protecti	ive devi	ces or affect upsti	ream/do	wnstream plants?	
✓ Caus	se the use of new or modified	equipme	nt [which is other t	than inkind]?	·		·		•	
Alter	equipment siting, building, tr	ailer locat	ions, roads or fire	protection?	?						
	ire modifying existing and/or			•							
Section 2	, 0						Si	multaneously Beg	in Cons	truction and Start-up)
			Dept./Pe	reon		Date		, ,		I	
Stage 1	Pre-Implementation		Respon			Complete		Completed By		Reference	s
'	Design Review		Taylor, Patrick			###########	Taylor	, Patrick J.			
	Process Engineering Review	v	, .					,			
	Instrumentation Review	-	Ketner, Joseph	Α.		#########	Ketne	r, Joseph A.			
	Control System Review		, , , , , , , , , , , , , , , , , , , ,					,			
	Utilities Review										
	Environmental/Regulatory F	eview	Chamberlin, Ro	bert T.		#########	Perez	, Carlos			
	Safety/Regulatory Review		Kirby, Anthony A.			######################################	Kirby, Anthony				
	Building Permits Review		Tuma, Dennis A.		-	#########		Tuma, Dennis A.			
	Mechanical Review				- +	******************	Tania				
	Inspection Review		Beauregard, Jo	hn T		#########	Beaur	Beauregard, John T.			
	Metallurgy Review		Prasad, Praneil		-	#########		d, Praneil-Mahara	i		
	Contruction Review		Costa, Steve W			#########		. Steve W.	J		
	Leak Seal Review		Costa, Oteve V	v .	-+	*******	00314	, oteve vv.			
	Relief System Review					#########	Muha	Edward			
	Infrastructure Review	<u> </u>			- 	***************************************	Widina,	Lawara			
	PHA/HSE Review		Simmons, Core	21/	- 1	#########	Simm	ons, Corey			
	T TO GITTOL TROVIOU		animone, corey		0						
Authoriza	ation to Implement Change (E	legin Con	struction): A	Approver:	Preciac	lo, Silvano E		[Date: 1	1/21/2012	
			Dant /Da			Data				I	
Stage	Pre-Startup		Dept./Pe Respon			Date Complete		Completed By		References	s
2	Procedures Review		Bessire John F		-	Complete					
	Communication/Training 1		Bessire, John F		<u> </u>	#########	Bessir	re, John P.			
	Pre Start-up Safety Review		Simmons, Core					,			
	The otalit up outery review		Similario, core	- 1							
Authoriza	ition to Start-Up Change:		F	Approver:					ate:		
Evtoneio	on of Temporary Change	Δnr	prover:				IEvn	iration Date:	I Evto	ntion Reason	1
Approve		174	olovei.				-^₽	iration bate.	LAC	ntion reason	
	· / ·								<u> </u>		
Stage	Post-Startup		Dept./Pe			Date		Completed By		References	
3	<u> </u>		Respon	sible	_	Complete		Oompicted By		NCICICIOC.	•
Communication/Training											
Process Safety Information											
Change in Place - Reviews, Approver: Date:											
Documentation & Testing Complete											
			ovor:								
MOC Cancelled: Approv											
		Cand	ellation Reason	l.							
Note 1:	Emergency request for c	nange sh	ould be routed	by the App	prover	on the next	workii	ng day Reta	in Origir	nal in Division for five Y	ears

DESIGNS REVIEW CHECKLIST

You have been assigned a Design Engineering Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number	25789
Filing Reference	
Person Responsible	Taylor, Patrick J.
Completed by	Taylor, Patrick J.
Date Completed	11/21/2012

Project/Equipment Description:

To replace process piping damaged by the 4 Crude Unit fire in 2012. Includes the TAW's that apply to the various process piping systems which had material changes, e.g., 5CR to 9CR.
This MOC covers the upgrade of piping systems from carbon steel to 9 Chrome. These piping systems include 3 side cut, 4 side cut, reboiler bypass piping, C-1100 bottoms piping, and C-1100 inlet transfer line.

TAW# - 17271, 17311, 17312, 17531, 17532, 17548, 17568, 17598, 17598, 17600, 17604, 17621, 17622, 17623, 17812, 17826, 17832, 17844, 17848, 17849, 18237, 18319, and 18405.

BIN Best Practic Civil & Structural Equipment Data Sheet Equipment Specification Fire Protection Hot Tap P&ID's Change due to New / Modified equipment Plot Plan Seismic SIS Update Temporary Leak Repair EQUIPMENT REVIEW Columns & Pressure Vessels Compressor, Blowers & Mechanical Equipment Concrete & Steel Structure, Walks and Stair Control Rooms & Building Exchangers, Condensers, Heaters & Cooling Tower Facilities & Siting Foundation Sewers, Roads & Miscellaneous Furances & Boilers Honeywell Honeywell Process Simulator Utility Systems		
Civil & Structural Equipment Data Sheet Equipment Specification Fire Protection Hot Tap P&ID's Change due to New / Modified equipment P&ID's Change - Field condition not matching existing P&ID Plot Plan Seismic SIS Update Temporary Leak Repair EQUIPMENT REVIEW Columns & Pressure Vessels Compressor, Blowers & Mechanical Equipment Concrete & Steel Structure, Walks and Stair Control Rooms & Building Exchangers, Condensers, Heaters & Cooling Tower Facilities & Siting Foundation Furances & Boilers Honeywell Honeywell Process Simulator	ENGINEERING REVIEW	
EQUIPMENT REVIEW □ Columns & Pressure Vessels □ Instrumentation □ Compressor, Blowers & Mechanical Equipment □ Insulation □ Concrete & Steel Structure, Walks and Stair □ Noise □ Control Rooms & Building □ Piping □ Exchangers, Condensers, Heaters & Cooling Tower □ Pumps & Drivers □ Facilities & Siting □ Relief & Venting Systems □ Sewers, Roads & Miscellaneous □ Furances & Boilers □ Tanks □ Update Refinery Relief Study	 □ BIN Best Practic □ Civil & Structural □ Equipment Data Sheet □ Equipment Specification □ Fire Protection □ Hot Tap ✔ P&ID's Change due to New / Modified equipment ✔ P&ID's Change - Field condition not matching existing □ Plot Plan □ Seismic 	P&ID
EQUIPMENT REVIEW □ Columns & Pressure Vessels □ Instrumentation □ Compressor, Blowers & Mechanical Equipment □ Insulation □ Concrete & Steel Structure, Walks and Stair □ Noise □ Control Rooms & Building □ Piping □ Exchangers, Condensers, Heaters & Cooling Tower □ Pumps & Drivers □ Facilities & Siting □ Relief & Venting Systems □ Sewers, Roads & Miscellaneous □ Furances & Boilers □ Tanks □ Update Refinery Relief Study	·	
Compressor, Blowers & Mechanical Equipment Concrete & Steel Structure, Walks and Stair Control Rooms & Building Exchangers, Condensers, Heaters & Cooling Tower Facilities & Siting Foundation Furances & Boilers Honeywell Honeywell Process Simulator		
	Compressor, Blowers & Mechanical Equipment Concrete & Steel Structure, Walks and Stair Control Rooms & Building Exchangers, Condensers, Heaters & Cooling Tower Facilities & Siting Foundation Furances & Boilers Honeywell	 Insulation Noise ✓ Piping Pumps & Drivers Relief & Venting Systems Sewers, Roads & Miscellaneous Tanks Update Refinery Relief Study

SUMMARY OF REVIEW*

The piping that is captured under this MOC is primarily replacement in kind, with a metallurgical upgrade to 9cr-1mo for increased corrosion resistance. The previous pipe class was either A, AE, B, BA, TF1, or TF2. The new pipe class which is being installed is "QF2". This pipe class has properties at temperature better than (higher pressure/temperature) the previous piping installed.

All piping upgrades to chrome had a full stress analysis completed in accordance to CES guidelines. This included an evaluation of the pipe stress, support reaction loads, and nozzle loadings. One line routing modification was made (0955-007-001) to more efficiently route the piping. This resulted in an additional spring hanger and the removal of a pedestal support at grade.

The other material upgrade that was completed was the auxiliary piping welded to the hot pump cases. This includes the hot pumps in the fire affected area with piping directly welded to pump the cases. The justification for using Inconel 625 was to allow this welding to take place while not requiring a post weld heat treatment (PWHT) of the pump case. The material is an upgrade to the existing CS piping, and the approved weld procedure for this weld (pump case to Inconel) is in accordance to ASME Section IX. The specification breaks for this piping is designed to be at the flange separating the plant piping (drain, warm-up, or vent) and the pump piping. All of these items are shown on the attached PSI documentation.

*When possible include copies of documents referenced in the summary.

INSTRUMENTATION REVIEW CHECKLIST

You have been assigned a Instrumentation Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number	25789
Filing Reference	
Person Responsible	Ketner, Joseph A.
Completed By	Ketner, Joseph A.
Date Completed	11/18/2012

Project/Equipment Description:

INISTRUMENTATION:

To replace process piping damaged by the 4 Crude Unit fire in 2012. Includes the TAW's that apply to the various process piping systems which had material changes, e.g., 5CR to 9CR.

This MOC covers the upgrade of piping systems from carbon steel to 9 Chrome. These piping systems include 3 side cut, 4 side cut, reboiler bypass piping, C-1100 bottoms piping, and C-1100 inlet transfer line.

INSTRUMENTATION.
☐ Alarm Objective Analysis
✓ Analyzer Instruments
☐ Chevmon
✓ Control Valves
✓ DCS
☐ Egatrol
✓ Electrical One-lines
✓ Field Installation
Flow Measurements
✓ Honeywell
Honeywell Process Simulator
✓ Instrument Seals, Purges, and Winterizing
✓ Level Measurements
✓ Loop Diagrams
✓ P&ID Change due to New / Modified equipment
✓ P&ID's Change - Field condition not matching existing P&ID
✓ Pressure Measurements
✓ Process Alarms
✓ Process Control
☐ Relief Systems
✓ Shutdown Systems
✓ Temperature Measurements

Sl	J١	ИI	M٨	٩R	Υ	OF	R	Έ	VI	E	W	*
----	----	----	----	----	---	----	---	---	----	---	---	---

All instrumentation damaged or destroyed in the fire will be repaired and / or replaced or upgraded as outlined in a TAW package.

*When possible include copies of documents referenced in the summary.

ENVIRONMENTAL REGULATORY REVIEW CHECKLIST

You have been assigned a Regulatory Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

Filing Reference:	
Person Responsible:	Chamberlin, Robert T.
Completed By:	Perez, Carlos
Date Completed:	11/21/2012

Project/Equipment Title:

4 Crude Recovery - Process Piping Systems Material Changes	
Check that all Apply:	SUMMARY OF REVIEW*
Chevron:	This MOC is for the Metallurgy changes to piping only, as discussed with the ABU future

Correction or Alternations to Refinery Utility System (RI-503)

Yellow Book

CITY OF RICHMOND CEQA (EIR's, etc

City of Richmond Conditional Use Permits (Land use and Hazardous Materials)

Regulatory

BAAQMD Air Regulations Permits (including Title V)

▼ BAAQMD Air Regulations: Additions, modifications, or deletions of VOC Components/Equipment (reg. 8-18 LDAR Program - equipment leaks/fugitive emissons)

BAAQMD Air Regulations: Wastewater System components - reg 8-8 and NSPS QQQ (process drains, catch basins, manholes, sumps, cleanouts, oil-water separators)

BAAQMD Air Regulations: Storage Tanks

BAAQMD Air Regulations: Internal Combustion Engines

BAAQMD Air Regulations: Flares

BAAQMD Air Regulations: Boiler, Steam Generators, Process

Heaters & Gas Turbines

BAAQMD Air Regulations: SRU, Tail gas, or H2S Unit Changes

BAAQMD Air Regulations: Long Wharf (Marine Terminal)

Department of Transportation (DOT)

This MOC is for the Metallurgy changes to piping only, as discussed with the ABU future MOC for piping installation will have to address VOC tagging of flanges and valves and ensure that all hazardous materials and sludge are removed from the scrapped pipe and equipment prior to sending to Reclamation for recycle or storage.

MOC Number: 25789

No other environmental regulatory issues.

*When possible include copies of documents referenced in the summary.

ENVIRONMENTAL REGULATORY REVIEW CHECKLIST

You have been assigned a Regulatory Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number:	25789
Filing Reference:	
Person Responsible:	Chamberlin, Robert T.
Completed By:	Perez, Carlos
Date Completed:	11/21/2012

Project/Equipment Title:

4 Cru	ide R	ecovery - Process Piping Systems Material Changes
		EPA Benzene NESHAP (National Emissions Standards for Hazardous Air Pollutnats) (process vents, storage tanks, watewater systems, transfer operations, fugitive emissions
		EPA Benzene Waste Operations NESHAP (BWON)
		EPA MACT (Maximum Achievable Control Technology) Standards and Subparts (process inits, storage tanks, wastewater system, fugitive emissions)
		EPA NSPS (New Source Performance Standards) and Subparts (storage tanks, flares, wastewater components, fugitive emissions, boilers, process heaters)
		Chemical Inventory / Hazardous Materials Business Plan (e.g. New Chemicals:RI-313)
		Risk Management and Prevention Plan (RMPP)
		RWQCB Waste Discharge Orders, EPA Consent Agreement Sites
		RWQCB NPDES Regulations/Permits
		RWQCB SB-1050, Waste Discharge Requirements (WDR)
		Spill Prevention Control and Counter Measures Plan (SPCC Plan)
✓		Waste Regulations and Permit
		Wharf and Shoreline Permitting related agencies (BCDC, Army Corps, SLC, USCG, OSPR, EPA)
		Permit to Build and Remove Wells, County Permit Required
		Activities impacting groundwater protection system (GPS) or WDO sites
Yes	No	
	✓	Any additions, modifications, or deletions of VOC Components/Equipment (including drains or wastewater components) that will change VOC identification/tag

SAFETY/ENVIRONMEMTAL REVIEW CHECKLIST

You have been assigned a Regulatory Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

Project/Equipment Title:

Crude Recovery - Process Piping Systems Material Changes	

Yes	No	Health & Safety Regulatory Review:
	V	Changes to Refinery Instructions
	v	Cal OHSA Construction Activity Permits
✓		Meets Legal and SID Requirements
	✓	Hazardous Materials Business Plan Changes
	✓	Special OSHA Notifications Required
	✓	Impacts RMP
	~	Additional Record Keeping Requirements

SUMMARY OF REVIEW*

Process piping will be replaced close to same locations as previous. SID audits will be conducted throughout rebuild to assure compliance.

MOC Number 25789

Person Responsible Kirby, Anthony A.

Date Completed 11/21/2012

Completed By Kirby, Anthony

Filing Reference

BUILDING PERMITS REVIEW CHECKLIST

You have been assigned a Regulatory Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

Project/Equipment Title:

4 Crude Recovery - Process Piping Systems Material Changes	

SUMMARY OF REVIEW*

Based on the information provided, no City of Richmond building permit required for the installation of process piping. Structural pipe supports do require a City of Richmond building permit.

MOC Number 25789

Person Responsible Tuma, Dennis A.

Date Completed 11/19/2012

Completed By Tuma, Dennis A.

Filing Reference

INSPECTION REVIEW CHECKLIST

You have been assigned a Inspection Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number	25789
Filing Reference	
Person Responsible	Beauregard, John T.
Completed By	Beauregard, John T.
Date Completed	11/21/2012

Project/Equipment Description:

To replace process piping damaged by the 4 Crude Unit fire in 2012. Includes the TAW's that apply to the various process piping systems which had material changes, e.g., 5CR to 9CR.

This MOC covers the upgrade of piping systems from carbon steel to 9 Chrome. These piping systems include 3 side cut, 4 side cut, reboiler bypass piping, C-1100 bottoms piping, and C-1100 inlet transfer line.

INSPECTION:
☐ Additional Surveillance Required
☐ API Standards
☐ ASME Codes & Standards
☐ ASTM Standards
☐ Control Monitoring Requirements
☐ Electrical Inspection
☐ Fitness for Service Evaluation
☐ Honeywell
☐ Honeywell Process Simulator
☐ Inspection/Monitoring Requirements
☐ Non-Destructive Examination
☐ Normal Control Requirements
☐ Positive Materials Indentification
\square Relief and Pressure Relief Devices Setting and Capacity
☐ Texas Nuclear (Metallurgy)
☐ UT Testing
☐ VOC Tagging Requirements

SUMMARY OF REVIEW*

Following Material engineering review the optimal choice for the high temperature piping in the Richmond 4 Crude unit was found to be 9Cr at the 3 and 4 S/C systems directly off the column is my understanding.

CML evaluation will be performed by the FER area inspector for the Crude Unit to determine if any of the data points should change. Changes include relocating, increasing and decreasing the total number and frequency. Crude Unit SME manuals and Refinery piping guidelines will be the instructional tools used to determine the amount and location of CMLs. Base line readings will be required. Chevron weld inspection is following the NDE on the newly installed piping circuits.

*When possible include copies of documents referenced in the summary.

METALLURGY REVIEW CHECKLIST

You have been assigned a Metallurgy Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number	25789
Filing Reference	
Person Responsible	Prasad, Praneil-Maharaj
Completed by	Prasad, Praneil-Maharaj
Date Completed	11/21/2012

Project/Equipment Description:

To replace process piping damaged by the 4 Crude Unit fire in 2012. Includes the TAW's that apply to the various process piping systems which had material changes, e.g., 5CR to 9CR.

This MOC covers the upgrade of piping systems from carbon steel to 9 Chrome. These piping systems include 3 side cut, 4 side cut, reboiler bypass piping, C-1100 bottoms piping, and C-1100 inlet transfer line.

TAW# - 17271, 17311, 17312, 17531, 17532, 17548, 17568, 17598, 17599, 17600, 17604, 17621, 17622, 17623, 17812, 17826, 17832, 17844, 17848, 17849, 18237, 18319, and 18405.

Refinery Process Stream:	Crude Unit		
Service Description:	Hydrocarbon (Crude)		
Process:	Hydrocarbon		
Other:			
Operating Tempature:		Operating Pressure:	
Design Tempature:		Design Pressure:	
Product Form:		Piping Classification:	
Equipment		Other:	
New Material Type:	9 Cr-1 Mo	Other:	
Connection for	Piping Specification:		Stress Relieved
Piping Spo	cification Comment:		
If Require	l, what is stress relieving temperat	ture: and	Time
Exchanger Bundle (Che	ck all Applicable)		
U-Bend	Γube Bundle □ U-Ben	nd Area Stress Relieved?	
\Box Finned \Im	ube Bundle	d Area Stress Relieved?	
\square Straight	Tube		
	eet and tubes made of different allo	, , , , , , , , , , , , , , , , , , ,	
\square Cladded	Tube sheet. Which side is clad?		
Other _			
Specification Change:			
Other:	chromium content in material helps increased resistance to high temperadeg F above CS. Inconel 625 pipin vent/drain connections, since this m to 9 Cr piping. Inconel 625 has increacking, which minimize issues du	ent in the Crude Unit is High Temper resist the degradation caused by this ature sulfidation and provides an open g was chosen to transition the carbon nitigates the need for a PWHT if a CS reased resistance to chloride pitting arring startups and shutdowns of the un material is essentially immune to hig	mechanism. 9 Cr provides rating temperature range 200 steel cases to 9 Cr piping on pump case was directly welded ad chloride stress corrosion it where liquid water can

CONSTRUCTION REVIEW CHECKLIST

You have been assigned a Construction Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number	25789
Filing Reference	
Person Responsible	Costa, Steve W.
Completed By	Costa, Steve W.
Date Completed	11/21/2012

Project/Equipment Description:

To replace process piping damaged by the 4 Crude Unit fire in 2012. Includes the TAW's that apply to the various process piping systems which had material changes, e.g., 5CR to 9CR.
This MOC covers the upgrade of piping systems from carbon steel to 9 Chrome. These piping systems include 3 side cut, 4 side cut, reboiler bypass piping, C-1100 bottoms piping, and

This MOC covers the upgrade of piping systems from carbon steel to 9 Chrome. These piping systems include 3 side cut, 4 side cut, reboiler bypass piping, C-1100 bottoms piping, and |C-1100 inlet transfer line.

CONSTRUCTION:		SUMMARY OF REVIEW*
☐ Building Permits	☐ Site Specific Hazards	Material Change only. Pipe Size and Routing does not change
☐ Construction Limitations	☐ Site Limitations	
\square Coordination with Multiple Plant	☐ Soil Removal	
☑ Coordination with Plant Protection	☐ Traffic Control	
✓ Cranes	✓ Weather	
☑ Equipment Drawings		
☐ Fire Protection Access/Requirement		
☐ Honeywell		
☐ Honeywell Process Simulator		
✓ Hot Work		
☐ Lay Down		
☐ Personnel Qualification/Training		
Piles		
☑ Plot Plan		
Restricted Area Classifications		
Schedules		
		I and the state of

*When possible include copies of documents referenced in the summary.

Monday, November 26, 2012

RELIEF SYSTEM REVIEW CHECKLIST

You have been assigned a Relief System Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number	25789
Filing Reference	
Person Responsible	Muha, Edward
Completed By	Muha, Edward
Date Completed	11/21/2012

Project/Equipment Description:

To replace process piping damaged by the 4 Crude Unit fire in 2012. Includes the TAW's that apply to the various process piping systems which had material changes, e.g., 5CR to 9CR.

This MOC covers the upgrade of piping systems from carbon steel to 9 Chrome. These piping systems include 3 side cut, 4 side cut, reboiler bypass piping, C-1100 bottoms piping, and C-1100 inlet transfer line.

RELIEF SYSTEM		SUMMARY OF REVIEW*
☐ Abnormal Heat Input	✓ Material of Construction	Changing the material of construction in the relief system will not effect the performance of the relief system. Change in the piping diameter or schedule will need to be reviewed by relief system
☐ Blocked Outlet	\square P & ID and Isometric Update	SME.
☐ Chemical Reaction	☐ Power Failure	
☐ Columns & Pressure Vessels	☐ Reflux Failure	
☐ Cooling Failure	Relief Study Update	
☐ Entrance of Volatile Material	Relief Valve Back Pressure	
☐ Heat Exchanger Tube Rupture		
☐ Honeywell		
☐ Honeywell Process Simulator		
☐ Hydraulic Expansion		
☐ Inadvertent Operating of Manual Valve		
☐ Instrument Air failure		
☐ Internal Explosion		
\square Loss of Upstream Heating		

*When possible include copies of documents referenced in the summary.

Monday, November 26, 2012

INSPECTION REVIEW CHECKLIST

You have been assigned a Inspection Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number: 25789

Completed On: 11/20/2012

Completed By: Bosworth, Gregory A.

Person Responsible: Bosworth, Gregory A.

Project/Equipment Description:

To replace process piping damaged by the 4 Crude Unit fire in 2012. Includes the TAW's that apply to the various process piping systems which had material changes, e.g., 5CR to

This MOC covers the upgrade of piping systems from carbon steel to 9 Chrome. These piping systems include 3 side cut, 4 side cut, reboiler bypass piping, C-1100 bottoms piping, and C-1100 inlet transfer line.

s]]]]	No	Plant Protection/Security Review City Fire-Plan Review is Mandato City Fire-Permit is Mandato City Acceptance Test is Mandato Office of Fire Prevention Review On	Your project must reviewed by the Richmond Fire Marshal before work can begin. Please call 2-4568 for additional details. Scope of work may require a hot work permit (open flame or no-open flame). Please call 2-4200 and request a job review /hot work permit.

*When possible include copies of documents referenced in the summary.

HEALTH & SAFETY EVALUATION

Date Issued:	11/17/201	12		MOC Number	25789	
ABU: D&R				Filing Reference		
Plant: 4 Crude				Person Responsible	Simmons, Corey	
Section 2	Reviewer:	Preciado, Silva	no E.	Completed By	Simmons, Corey	
Project/Equip	ment Title:	4 Crude Recov	very - Process Piping Systems Material Change	Date Completed	11/21/2012	
Description: To replace process piping damaged by the 4 Crude Unit fire in 2012. Includes the TAW's that apply to the value of piping systems from carbon steel to 9 Chrome. These piping systems include Step 1: USW Representation Present USW Representative: Al Cruz			n steel to 9 Chrome. These piping systems include 3 side cu	, ,		
Worker's Cor	mmittee Men	mber/Steward's	comments if unable to attend:			
Γ	Notify Tra	niner T	rainerRepresentation Present Training	g Representative: Phil Bessire		
Step 2: In	volve: Oper	rations, Mainte	nance, Technical and others with appropria	ite expertise relevant to the change (CRTC, Contractors,	etc)	
Attendees:				Sohnrey, Al Cruz, Mike Story, Ronad McCallum, Praneil Prasad, T		
Step 3: The training requi			I. Discuss the existing situation. Discuss t	he change. Discuss the impact of the change on the exi	isting situation. Determine the	
Step 4:				Training Type: 1		
•			ur options, consider your following:			
		: *Benzene *Fa	• •	k *Confined Space Entry *Evacuation Plan *Safety Operator	Proceed	
•	Concern		Consequence	Mitigation	Safely	
Is 9CR differ	rent in cleani	ing the piping?	Could be different	No, it's the same as Carbon Steel	Yes	
Blinds get ta	aken out		Could install wrong blind, corrision failure	Need to stamp 9Cr blinds	Yes	
Spec blinds	wrong mater	rial	Corrision failure, flange leak	Update routine duty for drop out spools to correct material is in place	identify Yes	
Clean up pro material (90	ocedures to r CR)	match	Could clean up wrong, affect piping	Identify piping system materials	Yes	
	product at sp mperature re		Increase degradation of lesser alloy.	Will be handled on another MOC	Yes	
HSE Action It	tems					

HEALTH & SAFETY EVALUATION

Date Issued:	11/17/20:	12	Maximo Number:	MOC Number	25789
ABU:	D&R		EWO Number	Filing Reference	
Plant:	4 Crude		_	Person Responsible	Simmons, Corey
Section 2	Reviewer:	Preciado, Silvano E.		Completed By	Simmons, Corey
Project/Equipn	ent Title:	4 Crude Recovery - Proc	cess Piping Systems Material Changes	Date Completed	11/21/2012
material changes, e.g., 5		material changes, e.g., ! This MOC covers the upo	grade of piping systems from carbon steel to 9 Chrom	,	, , ,
9CR can handle hi	gher temperati	ures. Being used in fire affected	l areas.		

Stage Two Training and Communication Review

11/26/2012 12:16:56 PM

	MOC No:	25789
Identify the affected employees.* Maintenance and Technical affected?	Date Completed:	11/22/2012
 Employee who will require training to start up the change based on the level of training. 	Completed By:	Bessire, John P.
* Employees who will receive training after the start up BUT	Person Responsible: Project/Equipm	Bessire, John P.
before they can perform work affected by the change Procedures have been modified/written (Ops/SSO/Trainer)	4 Crude Recovery - Process Piping Systems Material Changes	
Identify the affected employees Lesson plan cover sheet (includes training objective statement and list of affected employees) Procedural changes (Standing Orders, mark-ups)	Summary of Review: Most of this piping is replacement in kind with a metalluary up	
* Flow daigrams (final or mark-ups) Determine level of training	grade from carbon	steel to 9 chrome
 ☑ Training has been scheduled ☑ Affected employees have been trained in order to start up the change. 		